

# INSTALLING MANUAL FOR CNC SWITCH FOR RS 100 / RS Z 100

1. CNC SWITCH IS THE UNIVERSAL PARTS WHICH ONLY CAN BE INSTALLED ON THE CARBURETOR TYPE SCOOTERS.
2. IF FI TYPE SCOOTER, NO NEEDS TO INSTALL THIS ACCESSORY.

1ST PHOTO




THE POSITION OF LOCK

1ST ACCESSORY



2ND PHOTO




USE LOCKTIE TO FASTEN SCREW

FINISHED PHOTO



1ST PHOTO




FIRST, ADJUST ANGLE BY TOOL.

2ND ACCESSORY



2ND PHOTO



THE POSITION OF BUSH

FINISHED PHOTO

