




SMAX CNC把手開關加油座組安裝說明

INSTALLING MANUAL FOR CNC SWITCH FOR SMAX 155



開關左右各有凹槽如下方圖1

THERE IS THE GROOVE ON THE LEFT & RIGHT SIDE OF SWITCH AS PHOTO 1.




圖1
PHOTO 1.

請自行將膠條配件(4pcs)安裝至凹槽如下方圖2

PLEASE INSTALL RUBBER 4PCS INTO THE GROOVE AS PHOTO 2.




圖2
PHOTO 2.