




NOTICE:

SPRAY CUTTING FLUID AS MACHINING.
FLUID WILL PERMEATE INTO THE GAP
OF CARBON FIBER AND BODY.

THIS IS THE NORMAL CONDITION
THAT LITTLE FLUID WILL EVAPORATE
WITH TIME.



USE WIPER TO CLEAN IT.



BRAND-NEW AGAIN.

