


S-MAX CNC輕量化三角台安裝說明

CNC ALUMINUM STEERING STEM INSTALLING MANUAL FOR S-MAX 155



1. 安裝S-MAX CNC三角台，若間隙過大須加裝此墊片，若間隙無過大則無須安裝此墊片

1.NEED TO INSTALL THIS WASHER
IF THE GAP IS BIG. IF THE GAP IS NOT TOO BIG,
DON'T NEED TO INSTALL IT.



2. 墊片安裝位置如上圖紅圈處

2.THE POSITION OF THE WASHER IS
AS THE PHOTO ABOVE. (RED CIRCLE)